

Humidity / Temperature Monitors 800016, 800015, 800027

Simultaneously monitor both temperature and humidity on a large 3-3/16 x 2 1/2" display. Useful in incubators, refrigerators, desiccators, environmental chambers, labs, clean rooms, stock rooms, warehouses, factories, greenhouses, and outdoors. Recall min/max temperature & humidity readings over any time period. °C and °F selectable, stand or wall mount. Come with 1 AAA battery which lasts a full year. N.I.S.T. traceable certificate of compliance available.

Model 800016 reads temperature and RH on a dual display. Model 800015 adds an external temperature sensor on a remote probe and features a triple display of all 3 parameters. Model 800027 adds internal and external RH displaying all four parameters simultaneously.

DIM: 4 1/4" x 4" x 7/8" (110 x 102 x 20 mm). WEIGHT: 5 oz (142 g).



| | | 800016 | 800015 | 800027 |
|---------------|----------|-------------------------|----------------------------|--------|
| Range | Temp In | 0 to 50°C (32 to 122°F) | | |
| | Temp Out | | -50 to 70°C (-58 to 158°F) | |
| | RH | 10 to 99% | | |
| Resolution | Temp | 0.1°C | | |
| | RH | 1% | | |
| Accuracy | Temp | ±1°C (±2°F) | | |
| | RH | ±5% | | |
| Internal Temp | | ✓ | ✓ | ✓ |
| Internal RH | | ✓ | ✓ | ✓ |
| External Temp | | | ✓ | ✓ |
| External RH | | | | ✓ |

| No. | Description |
|-----|-------------|
|-----|-------------|

- | | |
|---------|--|
| 800016 | Humidity/Temperature Monitor |
| 800016C | Humidity/Temperature Monitor Certified |
| 800015 | Humidity/Temperature Monitor with Remote Temperature |
| 800015C | Humidity/Temperature Monitor with Remote Temperature Certified |
| 800027 | In/Out - Humidity Temperature Monitor |
| 800027C | In/Out - Humidity Temperature Monitor Certified |

