


Remote Relative Humidity (RH) Monitor and Digital Thermometer

The remote ambient temperature / relative humidity sensor is mounted on a cord over 4' long. Place the highly accurate sensor inside a desiccator, refrigerator, drying or other environmental chamber and view simultaneous displays of temperature and RH outside on the large LCD. Recalls min/max readings on both parameters. °C and °F selectable. Stands or wall mounts. N.I.S.T. traceable certificate of compliance available.

DIM: 4 1/4" x 3 3/4" x 7/8" (110 x 97 x 20 mm).

WEIGHT: 6 oz (170 g).



No.	Description
800027	Indoor/Outdoor Humidity/Temperature Monitor
800027C	Indoor/Outdoor Humidity/Temperature Monitor Certified

	Range	Resolution	Accuracy
Temperature In	0 to 50°C (32 to 122°F)	0.1°C/°F	±1°C (±2°F)
Temperature Out	-50 to 70°C (-58 to 158°F)		
Humidity In/Out	10 to 99%	1%	±5%

